




## **LEGEND**







■ TOP MOUNT POST


© CENTERLINE

F.F. FINISHED FLOOR

TYP TYPICAL CONDITION;
APPLIES ELSEWHERE AT
SIMILAR LOCATIONS

## NOTES:


TOP RAIL NOT SHOWN FOR CLARITY.



RAINIER TM42F

 $\mathcal{C}$ 

AGS



## NOTES:

- 1. DECK STRUCTURE CAN VARY GREATLY. IT IS THE RESPONSIBILITY OF THE CUSTOMER TO VERIFY THAT THE SUPPORTING STRUCTURE IS ADEQUATE TO MEET THE LOAD REQUIREMENTS OF THE GOVERNING BUILDING CODE(S). AGS Stainless Inc. RECOMMENDS CONSULTING A DESIGN OR CONSTRUCTION PROFESSIONAL TO ADDRESS THESE ISSUES.
- 2. POSITIVE CONNECTION TO ADJACENT STRUCTURE IS REQUIRED.




 $\mathcal{C}$ 


2

AGS

TOP MOUNT


42"






OUTSIDE CORNER POST LAYOUT - 90°
SCALE: NONE

B INSIDE CORNER POST LAYOUT - 90° SCALE: NONE





OUTSIDE CORNER POST LAYOUT - 45°
SCALE: NONE

D INSIDE CORNER POST LAYOUT - 45°
SCALE: NONE



NOTE:

THE LAYOUTS SHOWN MAY VARY AS THE ANGLE CHANGES. MAKE SURE YOU CHOOSE A POST LAYOUT SO THAT TWO CLOSEST POINTS OF THE ADJACENT POSTS IS LESS THAN 4".